Padrão Fotográfico SM 50 para tecidos

O SM 50 é constituído por uma série de padrões fotográficos para avaliação dos resultados em tecidos. Os padrões são constituídos por 4 séries de 5 fotos graduadas numericamente de 1 a 5 contendo em cada foto 4 exemplos de testes mostrando como se distribuem o Pilling e o Fuzzing nas amostras.

O SM 50 for woven fabrics – Martindale possui séries fornecidas em ligamentos denominados:

SM 50 - Twill White Background (5 imagens)

SM 50 - Twill Black Background (5 imagens)

SM 50 – Woven Blanket (5 imagens)

SM 50 – Plain Weave (5 imagens)

Atende às normas:

Norma	**Título**
ASTM D 4970	Standard Test Method for Pilling Resistance and Other Related Surface Changes of Textile Fabrics: Martindale Tester
BS EN ISO 12947-1	Textiles. Determination of the abrasion resistance of fabrics by the Martindale method. Martindale abrasion testing apparatus
EN ISO 12947	Textiles -- Determination of the abrasion resistance of fabrics by the Martindale method
IS 12673	Textile fabrics - Methods for determination abrasion resistance
ISO 12945-2	Textiles -- Determination of fabric propensity to surface fuzzing and to pilling -- Part 2: Modified Martindale method
ISO 12947-1	Textiles -- Determination of the abrasion resistance of fabrics by the Martindale method -- Part 1: Martindale abrasion testing apparatus
IWS TM 112	
IWS TM 196	
IWTO 40-88	
JIS L 1096	Testing methods for woven and knitted fabrics

SN EN ISO 12945-2	Textiles - Determination Of Fabric Propensity To Surface Fuzzing And To Pilling - Part 2: Modified Martindale Method
SN EN ISO 12947-1	Textiles - Determination Of The Abrasion Resistance Of Fabrics By The Martindale Method - Part 1: Martindale Abrasion Testing Apparatus
SN EN ISO 12947-2	Textiles - Determination Of Abrasion Resistance Of Fabrics By The Martindale Method - Part 2: Determination Of Specimen Breakdown
SN EN ISO 12947-3	Textiles - Determination Of The Abrasion Resistance Of Fabrics By The Martindale Method - Part 3: Determination Of Mass Loss
SN EN ISO 12947-4	Textiles - Determination Of The Abrasion Resistance Of Fabrics By The Martindale Method - Part 4: Assessment Of Appearance Change

Atende às necessidades dos seguintes aparelhos:

Abrasímetro Martindale TC 145 - 6 posições

Abrasímetro Martindale – JH

Pilling Tester TC 180-2

Pilling Tester TC 180-4

Cabine de observação TC 395

Cabine Proview JH